


GAS SAFETY RECALL



Macpac Micro-Stove

SKU 112253 and (Date of Manufacture) DOM 08/19

Sold at Macpac stores between 15 October 2019 and 21 December 2019

Defect: The gas product does not meet Australian regulations due to incorrect specifications: The threaded component may be difficult to connect to a butane canister.

Only micro-stoves that bear DOM and the inlet air hole as detailed above are affected. Other batches of micro-stoves without the inlet air hole are not affected.

Hazard: Gas can leak for longer than the expected short burst when screwing onto the canister. If this occurs near an ignition source, the released flammable gas may ignite resulting in a fire or serious illness, injury or death.

What to do: Stop using the product and return it to their nearest Macpac retail store for a refund. In addition to a refund, Macpac is offering customers a \$20 store voucher upon returning the product.

If it is not safe to return it to a Macpac retail store under Covid 19 restrictions, mark the product "DO NOT USE" and store securely until it is safe to return it to the nearest Macpac retail store.

Contact details: Macpac Australia
Telephone number – 1800 325 215 International - +64 (0)3 964 9693
Email customerservice@macpac.com.au

**See productsafety.gov.au for
Australian product recall information**